

Příloha č.6 –Tingleyho schéma

	A				C'				B			
	A'				C				B'			
Pól 1	1	3	5	7	9	11	13	15	17	19	21	23
	2	4	6	8	10	12	14	16	18	20	22	24
Pól 2	25	27	29	31	33	35	37	39	41	43	45	47
	26	28	30	32	34	36	38	40	42	44	46	48
Pól 3	49	51	53	55	57	59	61	63	65	67	69	71
	50	52	54	56	58	60	62	64	66	68	70	72
Pól 4	73	75	77	79	81	83	85	87	89	91	93	95
	74	76	78	80	82	84	86	88	90	92	94	96
Pól 5	97	99	101	103	105	107	109	111	113	115	117	119
	98	100	102	104	106	108	110	112	114	116	118	120
Pól 6	121	123	125	127	129	131	133	135	137	139	141	143
	122	124	126	128	130	132	134	136	138	140	142	144